
RECALL NOTICE

Flushmate II 501-B





FLUSHMATE is announcing the voluntary recall of Flushmate II 501-B units manufactured from September 3, 1996 through December 7, 2013.

Recalled Flushmate II 501-B units can burst at or near the vessel weld seam releasing stored pressure. This pressure can lift the tank lid and shatter the tank, posing impact and laceration hazards to consumers and property damage.

To verify if your unit is included in the Flushmate II 501-B recall, register your unit, and to request a free Flushmate replacement unit and installation by a technician, visit:

http://www.flushmate.com/501B-recall

Toll-free Flushmate II 501-B Recall Hotline: (844) 621-7538 8 AM - 10 PM ET, Monday - Friday 8 AM - 6:30 PM ET, Saturday



